



FIGURE II-32. Interior of Tank 21 by Periscope, 1971
Shows good condition of steel liner.
Angle iron stiffened ring, one foot
below top of wall, is 4 in. by 4 in.